



MATERIALS TESTING, INC.

55 LAURA STREET • NEW HAVEN, CONNECTICUT 06512 • (203) 468-5216
42 BOSTON POST ROAD • WILLIMANTIC, CONNECTICUT 06226 • (860) 423-1972

DATE: 05-09-16

REPORT: M-1093

CLIENT: McClure Construction Co.
PO Box 367
Waterford, CT 06385

PROJECT: Client's Information

SUBJECT: WASHED SIEVE ANALYSIS (ASTM C-136, D1140)

Material: Masonry Sand

Source: McClure, Groton Pit

Sampled: by client and delivered to MTI on 5/5/16



Sieve Size	Percent Passing	ASTM C-144 Specification
3/8" (9.5mm)	100	100
#4 (4.75mm)	100	100
#8 (2.36mm)	99	95-100
#16 (1.18mm)	88	70-100
#30 (600µm)	57	40-75
#50 (300µm)	20	10-35
#100 (150µm)	4	2-15
#200 (75µm)	1.1	0-5

This material as sampled and delivered meets the listed specification.

Materials Testing, Inc.
Richard C. Kearns

William J. Soucy

1cc: Client
1cc: J McClure

wlb