



MATERIALS TESTING, INC.

55 LAURA STREET • NEW HAVEN, CONNECTICUT 06512 • (203) 468-5216
42 BOSTON POST ROAD • WILLIMANTIC, CONNECTICUT 06226 • (860) 423-1972

DATE: 03-03-16

REPORT: M-1085

CLIENT: McClure Construction Co.
PO Box 367
Waterford, CT 06385

PROJECT: Client's Information

SUBJECT: SIEVE ANALYSIS (ASTM C-136)

Material: 3/8" Stone

Source: McClure Pit

Sampled: by client and delivered to MTI on 3/2/16


| <u>Sieve Size</u> | <u>Percent Passing</u> |
|-------------------|------------------------|
| 3/4" (19mm) | 100 |
| 1/2" (12.5mm) | 99 |
| 3/8" (9.5mm) | 77 |
| #4 (4.75mm) | 5 |
| #8 (2.36mm) | 3 |
| #16 (1.18mm) | 2 |

A material specification was not provided at this time.

Materials Testing, Inc.

Bryan Kearns

William J. Soucy



1cc: Client
1cc: J McClure

eaw